


Annual Electrical Safety Record - E2



Brooklyn House,
Money Lane,
The Green,
West Drayton,
UB7 7PQ
TEL : 0800 587 9999



Date : Tuesday, 15 January, 2013

Cert. No : CT-1011056-792776001

Client
Mrs Caroline Harris
The Pastures
6a Station Road
Nassington
Peterborough
Cambridgeshire

Site Address
Anvil Cottage
8 Cow Lane
Wareham
Dorset
BH20 4RD

INSTALLATION INSPECTION (Visual & Functional)

Electrical supply details

Supply : TN-C-S Phase : 1-Phase PIR/EICR Label present Yes Expired on 01/12/2006

Meter Reading 27803
Meter Visual Inspection Pass

Earthing Conductor	Main Protective Bonding Conductors	General Condition of Consumer Unit:-	Good
Water : Yes	Gas : Yes	RCD Test:-	Yes Zs 0.56 Ω

Circuit Number	Description	Functional Check	Protective Device	Recommendations
	Lighting upstairs, doorbell	Yes	BS (EN) 60898	6 amp
	Lighting downstairs	Yes	BS (EN) 60898	6 amp
	Smoke detector	Yes	BS (EN) 60898	6 amp
	Cooker point RCD	Yes	BS (EN) 60898	40 amp
	Sockets kitchen RCD	Yes	BS (EN) 60898	32 amp
	Sockets upstairs RCD	Yes	BS (EN) 60898	32 amp
	Sockets downstairs RCD	Yes	BS (EN) 60898	32 amp

COMPLIANCE DETAILS/ ELECTRICAL EQUIPMENT RESULTS

Location	Type	Make	Model	Serial No	Plug	Flex	Body	Continuity (ohms)	Insulation (megohms)	Functional Check	Comments	Passed Safety Test
Kitchen	Washer Dryer	Neff	V5340XDGB/04	2002052	Pass	Pass	Pass	0.10	N/C*	Pass	Class 1	Yes
Kitchen	Dishwasher	Neff	S5444X1GB/23	406050409119000645	Pass	Pass	Pass	0.16	N/C*	Pass	Class 1	Yes
Kitchen	Oven	Neff	B1422NOGB	N/F	N/Acc	N/Acc	Pass	0.19	N/C*	Pass	Class 1	Yes
Kitchen	Cooker Hood	Hygena	APP2440	3408050107	Pass	Pass	Pass	N/A	>20K	Pass	Class 2	Yes
Kitchen	Hob Ignition	Neff	N/F	N/F	Pass	N/Acc	Pass	0.15	N/C*	Pass	Class 1	Yes
Bedroom	Dryer	Hoover	HNC160-80	3110006704466316	Pass	Pass	Pass	0.09	>20K	Pass	Class 1	Yes
Bedroom	Extension Lead	N/F	N/F	N/F	Pass	Pass	Pass	0.08	>20K	Pass	Class 1	Yes

Details of any faults found and rectification work necessary

Warning Notice

No
No
No
No
No
No

This Safety Record Issued By



Inspection Due Within 12 Months

Name Wai Lee

This report is a general, visual, surface and functional examination of the electrical system, which is accessible i.e. visible and readily available for inspection from ground and floor levels without risk of causing damage to the property or injury to the inspector and limited accordingly. No liability is therefore exercised throughout the inspection regarding safety, practicality and the constraints of being a visitor to the property (which may be occupied). The client is responsible for the safety of the property, its contents, furniture, floor coverings and other contents are not moved, lifted and no part is forced or laid open to make it accessible. Loop impedance tests are only carried out on socket outlets. The report is provided solely for the use of the client and no liability to anyone else is accepted. The client not act upon specific advice contained in the report, no responsibility is accepted for the consequences. Gas-Elec Safety Systems, its employees or franchisees accept no liability for the consequences of any errors or omissions in this report.

THIS IS A VISUAL AND FUNCTIONAL INSPECTION ONLY

In the event of a complaint relating to any service or installation in a property gas-elec must be given the opportunity to address the issue by re-visiting the property to resolve any alleged complaint. gas-elec cannot be held responsible if the opportunity to fully address the matter is not afforded to us. In the event of another inspection by/contractor being called to the property to investigate or attempt to rectify an alleged complaint in preference to gas-elec the company will accept no liability. Where passed safety test is VO, this is an abbreviation of visual only inspection.

Annual Electrical Safety Record - E2



Brooklyn House,
Money Lane,
The Green,
West Drayton,
UB7 7PQ
TEL : 0800 587 9999



Date : Tuesday, 15 January, 2013

Cert. No : CT-1011056-79276001

Client
Mrs Caroline Harris
The Pastures
6a Station Road
Nassington
Peterborough
Cambridgeshire

Site Address
Anvil Cottage
8 Cow Lane
Wareham
Dorset
BH20 4RD

INSTALLATION INSPECTION (Visual & Functional)

Electrical supply details

Type : TN-C-S Phase : 1-Phase PIR/EICR Label present Yes Expired on 01/12/2006

Meter Reading 27803
Meter Visual Inspection Pass

Main Earthing Conductor

Main Protective Bonding Conductors

Present Water : Yes Gas : Yes Other :

General Condition of Consumer Unit:- Good

RCD Test:- Yes Zs 0.56 Ω

Circuit Number	Description	Functional Check	Protective Device	Recommendations
----------------	-------------	------------------	-------------------	-----------------

APPLIANCE DETAILS/ ELECTRICAL EQUIPMENT RESULTS

ID	Location	Type	Make	Model	Serial No	Plug	Flex	Body	Continuity (ohms)	Insulation (megohms)	Functional Check	Comments	Passed Safety Test
8	Kitchen	Fridge/Freezer	Hotpoint	FF200L	911264070	Pass	Pass	Pass	0.09	N/C*	Pass	Class 1	Yes

Details of any faults found and rectification work necessary

Warning Notice

8

No

This Safety Record Issued By

Next Inspection Due Within 12 Months * "(Please refer to the documents titled "E2 comments" for comments made by the engineer for this inspection)"

Name Wai Lee

The report is a general, visual, surface and functional examination of the electrical system, which is accessible i.e. visible and readily available for inspection from ground and floor levels without risk of causing damage to the property or injury to the inspector and limited accordingly.

Due care is therefore exercised throughout the inspection regarding safety, practicality and the constraints of being a visitor to the property (which may be occupied).

So furniture, floor coverings and other contents are not moved, lifted and no part is forced or laid open to make it accessible. Loop impedance tests are only carried out on socket outlets. The report is provided solely for the use of the client and no liability to anyone else is accepted.

Should the client not act upon specific advice contained in the report, no responsibility is accepted for the consequences. Gas-Elec Safety Systems, its employees or franchisees accept no liability for the consequences of any errors or omissions in this report.

THIS IS A VISUAL AND FUNCTIONAL INSPECTION ONLY

In the event of a complaint relating to any service or installation in a property gas-elec must be given the opportunity to address the issue by re-visiting the property to resolve any alleged complaint. gas-elec cannot be held responsible if the opportunity to fully address the matter is not afforded to us. In the event of another company/contractor being called to the property to investigate or attempt to rectify an alleged complaint in preference to gas-elec the company will accept no liability. Where passed safety test is VO, this is an abbreviation of visual only inspection.